

New Headers Have a special coating inside and will smoke badly until you get about 5 miles on the vehicle, also check your dipstick just to be sure system is not overfilled. We never have smoking problems with our engines.